

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,409,564 B2
APPLICATION NO. : 10/805753
DATED : August 5, 2008
INVENTOR(S) : Ken Kump et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 24, Line 44


Please replace claim 40 with the following:

40. A medical imaging system of claim 26, wherein the second trigger signal is a system timeout signal.

This certificate supersedes the Certificate of Correction issued December 23, 2008.

Signed and Sealed this

Twenty-seventh Day of January, 2009

A handwritten signature in cursive script that reads "John Doll".

JOHN DOLL
Acting Director of the United States Patent and Trademark Office